

Photo of the inside of the fire wall.



Photo of where the flue gases enter the wall, note the discolouration of the plaster wall.



Mob: 0400063625

Web: [www.plumbingbytim.com.au](http://www.plumbingbytim.com.au)

Email: [tim@plumbingbytim.com.au](mailto:tim@plumbingbytim.com.au)